

2010 the Deep Water Horizon encountered a blowout. The Blow Out Preventer should have prevented the following disaster but only partly worked. In this Event Map based on the US CSB animation we explain the chain of events.

## Location

Macondo well in the Gulf of Mexico

## Author

Bart Smit (CoThink

## Date of last update

21-2-2018

## Status description

The causes identified by the US CSB also apply to other BOP's in operation. The US CSB warned manufacturers of the risks of effective compression in drill pipes in BOP's.

